



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 04/09/2015

Reviewed

[Signature]

| | | |
|----------------------------------------|------------------------------|------------------------------|
| Mine Name: Eureka Rock | Permit Number: S/023/0094 | Mine Status: Active |
| Operator Name: Eureka Rock LLC | Inspection Date: 04/07/2015 | Permit Fees: Paid |
| Inspector(s): Wayne Western | Inspection Time: 11:50-12:05 | Bond Amount: \$20,800 |
| Attendee(s): none | Weather: sunny mild | Bond Escalation: 12/20/2014 |
| Inspection Purpose: Routine inspection | | Prior Inspection: 10/17/2013 |

Conclusions and Recommendations


The bond needs to be escalated from to 2014 to either 2017 or 2019. The annual reports have not been submitted. The last annual report was in 2011 when no production was reported.

| Elements of Inspection | Evaluated & Commented | Enforcement |
|------------------------------------------------------------------------------------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds The permit fees are current. The bond needs to be escalated from 2014. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (shafts, adits, trash, signs, highwalls) The highwalls appear to be stable. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages/Erosion Control There were no erosion problems at the site. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Roads (maintenance, surfacing, dust control, safety) The road to the mine was in stable condition. | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 6. Reclamation | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts) | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Soils | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Other | <input type="checkbox"/> | <input type="checkbox"/> |

Inspector's Signature: _____

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230094-EurekaRock/inspections/Insp-04072015.pdf



Excavator on site.



Looking south highwall on left.



Looking east at the highwall



Looking east at the highwall - notice the vegetation in the foreground.